

Title: Electrical Service Disconnect Having Tamper Detection Inventor: Holle et al. App. No. 10/085,426 Page 1 of 7 Replacement Sheet MAY 1 5 2006 THADEN REMOTE DEVICE COMMUNCATION CIRCUIT DISPLAY 23 **ACTUATOR** CONTROL INDICATOR <u> 1</u>80 132 SENSE CIRCUIT 120 102

Title: Electrical Service Disconnect Having Tamper Detection Inventor: Holle et al. App. No. 10/085,426 Page 2 of 7 Replacement Sheet MAY 15 2006 ANTE TRADES 56 ιũ 52 16_b 27 25 78 80 88 88ar 84 12_d 82 26 28 30e 30f 30d 30g 40 f 36 32 MAY 15 2006

Title: Electrical Service Disconnect Having Tamper Detection Inventor: Holle et al. App. No. 10/085,426 Page 3 of 7 Replacement Sheet







MAY 1 5 2006

Title: Electrical Service Disconnect Having Tamper Detection Inventor: Holle et al.

App. No. 10/085,426

Page 4 of 7 Replacement Sheet





Title: Electrical Service Disconnect Having Tamper Detection

Inventor: Holle et al. App. No. 10/085,426 Page 5 of 7 Replacement Sheet



